




Bloomfield Township Wetland Inventory Quality Assessment Map

FIGURE 3

Final Map

December 2007



Legend

▲ Photo Location

● Survey Location

◆ Township Outfalls

◆ Outfall Locations

◆ Detention Basins

Wetlands by Quality Assessment

■ Low Quality (Score 0 - 29)

■ Moderate Quality (Score 30 - 39)


■ Mod. High Quality (Score 39 - 49)

■ High Quality (Score 50 - 100)

■ Lakes

Note: Some colors on map have been made transparent for purposes of viewing all layers simultaneously. Therefore, colors in legend may appear slightly different than as displayed on the map.

This map shows the approximate location and existence of wetlands in Bloomfield Township as developed from Base Map data and a field evaluation primarily from public right-of-ways. This map is intended to be used as a tool to assist in indicating the possible presence of wetlands. The presence of wetlands as indicated is not intended to imply exact location or specific jurisdictional status or regulatory authority. Likewise, the absence of wetland on this map does not necessarily indicate that wetland is not present, but rather that the presence of wetland was found not likely during this inventory. Therefore, each site should be evaluated on a site specific basis. A permit is required from the Michigan Department of Environmental Quality and the Township to conduct certain activities in a regulated wetland. Bloomfield Township assumes no responsibility for errors that arise from the use of this data.



NISWANDER ENVIRONMENTAL, LLC



10524 E Grand River Ave., Suite 103
Brighton, MI 48116
810.225.0530 Fax: 810.225.0533